

Next Generation MistBuster®


is the best investment for a compact, energy efficient and reliable solution for capturing oil mist and smoke. To guarantee this continuously, professional maintenance and expertise is important. Filcom Filterservice Ltd offers support that ensures regular maintenance.



Service works include:

- Measurement of the MistBuster® electrical components
- Separate charging, measuring and - where possible - correcting the MistBuster® cells
- Remove dirt and oil from the cells, printed circuit boards (power supply) and ionizer / collector board
- Periodical replacement of the MistBuster® cells by cleaned and tested cells (building up the correct voltage)
- No more investment required for new filter cells and/or replacement of ionisation wires


Expert cell cleaning




Cell before cleaning



Cleaned cell



Cell before cleaning



Cleaned cell

Filcom Filterservice Ltd.

Unit 16 Stirlin Point
 Sadler Court, Lincoln
 LN6 3RG
 E: office.uk@filcom-group.com
www.filcom-group.com

SERVICE AGREEMENT

- Maintenance every 3 months
- Contract periode: 1 year (can be cancelled monthly thereafter)
- Including labour and travel on site
 Replacement of E-components & HEPA filter is not included

£ 49,00
 per month, per unit*

**ask for the conditions*

